



GH15B User Manual V4.0

Product Description



Foreword

Dear Users:

Welcome to use the GH15B fiber laser intelligent focusing cutting head products produced by Shenzhen Ospri Intelligent Technology Co., LTD. We are honored to have your confidence in our products.

In order to make you have an overall view of the product, convenient for your use, we specifically provide the user manual for you, including product characteristics, structural feature, technical feature, direction for use, maintenance, etc. It's an essential guide when you use this product.

Please read the user manual carefully before use. I'm sure it will be helpful for you to use this product. In addition, if you have any questions during use, please contact us, and we will serve you wholeheartedly.

Declaration:

The contents of User Manual are protected by the Copyright Law. Without the approval of Shenzhen Ospri Intelligent Technology Co., Ltd, any organization or individual shall not copy or tamper it by any means and forms.

In order to ensure your safety and the product works normally, please read the guide book carefully before using.

Contents

Chapter 1 Overview

1.1 Product Parameter.....	01
1.2 Precautions.....	01

Chapter 2 Structural Features

2.1 Brief Description of Product Structure	02
2.2 Brief Description of Product Parts	03
2.3 Brief Description of Product Parts (Lens Size)	04

Chapter 3 Product Installation

3.1 Cutting Head Installation	05
3.2 Pipeline Connection	06
3.2.1 Cooling Pipeline	06
3.2.2 Auxiliary Gas Pipeline	07
3.3 Wiring Definition and Requirements	08
3.3.1 Aviation Plug Connector	08
3.3.2 Overview of Pulse Wiring (Cypcut)	09
3.3.3 Servo Driver Power Connection (DC24V).....	09
3.4 FSCUT2000C System Wiring (Example: BCL3766).....	10
3.4.1 Board I/O Wiring.....	10
3.4.2 Cypcut Open Loop Card I/O Wiring.....	11
3.4.3 Driver Parameter Settings.....	11

3.5 Overview of Bus Wiring (Cypcut)	12
3.5.1 Servo Driver Power Connection (DC24V)	12
3.6 FSCUT8000 System Wiring (Example: HPL2720E)	13
3.6.1 Board I/O Wiring (Example: HPL2720E)	13
3.6.2 Driver Parameters.	14
3.7 Overview of Open Loop Wiring (Weihong)	15
3.7.1 Servo Driver Power Connection (DC24V)	15
3.8 LS6000M Non-Bus System Wiring (Example: EX41A)	16
3.8.1 Board Wiring	16
3.8.2 Weihong Open Loop Card I/O Wiring	17
3.8.3 Driver Parameters	17
3.8.4 Signal Line Wiring	18
3.8.5 Bus Module Wiring Instructions	18
3.9 Overview of Bus Wiring (Weihong)	19
3.9.1 Servo Driver Power Connection (DC24V)	19
3.10 LS6000M Bus System Wiring (Example: EX41A)	20
3.10.1 Board Wiring	20
3.10.2 Driver Parameters	21
3.10.3 Signal Line Wiring.	22
3.10.4 Toggle Switch Status	22
3.10.5 Bus Module Wiring Instructions	23
3.11 Q+ Fiber Laser Head Installation	24

Chapter 4 Product Debugging

4.1 Focusing Instructions (Example: FSCUT2000C (Pulse System)).....	25
4.1.1 GH15/20/30B Cypcut Platform Configuration.....	25
4.1.2 Alarm Signal Configuration.....	27
4.2 FSCUT8000 System Configuration (Bus System).....	28
4.2.1 Focus Control Configuration and Limit ConfigurationV28	
4.2.2 Alarm Signal Configuration.....	30
4.3 LS6000M Non-Bus System Configuration.....	31
4.3.1 W-Axis Parameter Configuration.....	31
4.3.2 W-Axis Alarm Signal Association.....	33
4.4 LS6000M Bus System Configuration.....	35
4.4.1 W-Axis Parameter Configuration.....	35
4.4.2 W-Axis Alarm Signal Association.....	37
4.5 Description of alignment adjustment.....	39
4.6 Mobile APP Operation Instructions	40
4.6.1 Mobile APP Installation	40
4.6.2 APP Software Connection	41
4.6.3 Software Introduction	42
4.6.4 Temperature Parameter Setting and Modification of Equipment Name.....	43

Chapter 5 Product Maintenance

5.1 Maintenance and Replacement of Protective Lens	45
5.1.1 Disassembly and Assembly of Collimation Protective Lens.....	45
5.1.2 Disassembly and Assembly of Focusing Protective Lens	49
5.1.3 Disassembly, Assembly, and Replacement of Cutting Protective Lens ..	51
5.2 Maintenance of Sensory Components	53
5.2.1 Replacement of Nozzle and Ceramic Body	53
5.2.2 Cleaning of Ceramic Body	53

Chapter 1 Overview

1.1 Product Parameter

① Product parameters, as shown in Table 1.0.

Name	Fiber Laser Cutting Head
Model	GH15B
Interface Type	QBH, QD, Q+, LOE/QF-D
Wavelength	1080±10nm
Rated Power	≤15KW
Focus Length	200mm/250mm/300mm
Collimation Length	100mm
Nozzle	Various models and specifications
Focusing range	-39mm~+30mm
Centering range	±1.5mm
Focusing speed	200mm/s
Gas Pressure	≤3Mpa
Weight	7KG

Table 1.0

1.2 Cautions

- ① Please wear specialized laser safety goggles to ensure human safety when the cutting head is used in coordination with laser cutting machine
- ② Precautions and standard operations should be taken to prevent burning of cutting head and laser nozzle due to the deviation of laser beam from central axis.
- ③ Keep the cutting head clean to prevent coolant, condensate or other foreign matter from entering sensor parts; otherwise, it may cause sensor failure.
- ④ When processing products with laser, use protective devices to prevent the laser beam from causing injury to human body.

Chapter 2 Structural Features

2.1 Brief Description of Product Structure

Brief description of product structure, as shown in Figure 1.0.




Figure 1.0

2.2 Brief Description of Product Parts

1. Q+ Interface: Connect the laser to the cutting head.
2. Collimation Protective Lens Module: When inserting and removing the fiber head, prevent dust from entering the cutting head to protect the collimator fiber laser tip.
3. Centering Knob: Adjust the optical path center to ensure the laser beam passes through the center of the nozzle.
4. Cutting Protective Lens Cartridge Module: Seal the cutting gas and protect the focus lens.
5. Water Cooling Connector: Mainly cool the components of the cutting head.
6. SMA Connector: Connect an external amplifier.
7. Focusing Protective Lens Cartridge Module: Protect the module of the focus lens and prevent dust from contaminating the focus lens directly.
8. Cutting Gas Interface: 10mm tube connection for cutting gas input during cutting.
9. Alarm Light: Alarm for collimating lens, focus lens, and protective lens temperature; protective lens in place alarm; cutting head air leak alarm.
10. Cooling Gas Inlet: 6mm tube connection for ceramic ring cooling.
11. Amplifier Mounting Plate: Adapter plate for mounting an external amplifier.





Figure 1.1

2.3 Brief Description of Product Parts (Lens Size)



Chapter 3 Product Installation

3.1 Cutting Head Installation

Cutting head installation dimensions (collimation F100/Focus F200) as shown in Figure 1.2.




Figure 1.2

3.2 Cutting Head Connection

3.2.1 Cooling Water Connection

- ① Used for cutting head cooling, one inlet and one outlet for the cooling pipeline, as shown in Figure 1.3.




Figure 1.3

3.2.2 Auxiliary Gas Pipeline.

- ① The inlet is connected to 10mm gas hose, as shown in the Figure 1.4, and is used to connect cutting gas, with inlet pressure <3.0 Mpa.
Common gas: Oxygen, nitrogen and compressed air.
- ② The inlet is connected to a 6mm gas pipe, as shown in Figure 1.4, and is used to connect cooling gas, input pressure <0.6 Mpa.
Common Gas: Compressed air.




Figure 1.4

Attention: The gas entering the gas connection must be filtered and dried, otherwise it will contaminate the protective lens and cause damage to it.

3.3 Wiring Definitions and Requirements

3.3.1 Aviation Plug Interfaces.

- ① When inserting and removing the aviation plug, cut off the power; otherwise, the motor may be burnt out. When connecting the power line and the signal line, pay attention to the notch position to avoid damage to the pin, as shown in Figure 1.5.





Figure 1.5

3.3.2 Overview of Pulse Wiring (Cypcut)





3.3.3 Servo Drive Power Connections (DC24V)




3.4 FSCUT2000C System Wiring (Example: BCL3766)

3.4.1 Board I/O Wiring



Limit switches and alarm signals are both NPN outputs; the alarm signal must be connected to the system. If damage to the cutting head occurs due to an unconnected alarm signal, the customer is fully responsible.


3.4.2 Cypcut Open Loop Card I/O Wiring




3.4.3 Driver Parameters

Parameter Index	Parameter Value	Parameter Content
PR007	10000	Pulses per revolution
PR008	4000	Resolution
PR015	0	Enable level
PR019	1	Motor direction
PR020	1	Bandwidth selection
PR042	6	Motor type

3.5 Overview of Bus Wiring (Cypcut)




3.5.1 Servo Driver Power Connection (DC24V)



3.6 FSCUT8000 System Wiring (Example: HPL2720E)

3.6.1 Board I/O Wiring (Example: HPL2720E)




Limit switches and alarm signals are both NPN outputs; the alarm signal must be connected to the system. If damage to the cutting head occurs due to an unconnected alarm signal, the customer is fully responsible.

3.6.2 Driver Parameters

Parameter Index	Parameter Value	Parameter Content
PA000	10000	Pulses per revolution
PA003	0	Rotation direction
PA411	81	Servo alarm logic (normally closed)
PR438	0	

Note: Electronic gear ratio numerator: 8192;
Electronic gear ratio denominator: 10000;
Encoder resolution: 13 bits;

3.7 Overview of Open Loop Wiring (Weihong)




3.7.1 Servo Driver Power Connection (DC24V)




3.8 LS6000M Non-Bus System Wiring (Example: EX41A)

3.8.1 Board Wiring



Limit switches and alarm signals are both NPN outputs; the alarm signal must be connected to the system. If damage to the cutting head occurs due to an unconnected alarm signal, the customer is fully responsible.


3.8.2 Weihong Open Loop Card I/O Wiring




3.8.3 Driver Parameters

Parameter Index	Parameter Value	Parameter Content
PR007	10000	Pulses per revolution
PR008	4000	Resolution
PR015	0	Enable level
PR019	1	Motor direction
PR020	1	Bandwidth selection
PR042	6	Motor type


3.8.4 Signal Line Wiring




3.8.5 Bus Module Wiring Instructions



3.9 Overview of Bus Wiring (Weihong)




3.9.1 Servo Driver Power Connection (DC24V)



3.10 LS6000M Bus System Wiring (Example: EX41A)

3.10.1 Board Wiring




Limit switches and alarm signals are both NPN outputs; the alarm signal must be connected to the system. If damage to the cutting head occurs due to an unconnected alarm signal, the customer is fully responsible.

3.10.2 Driver Parameters

Parameter Index	Parameter Value	Parameter Content
PA000	10000	Pulses per revolution
PA003	0	Rotation direction
PA411	81	Servo alarm logic (normally closed)
PR438	0	Slave source

Note: Electronic gear ratio numerator: 8192;
Electronic gear ratio denominator: 10000;
Encoder resolution: 13 bits;


3.10.3 Signal Line Wiring



3.10.4 Toggle Switch Status



3.10.5 Bus Module Wiring Instructions



3.11 Q+ Fiber Laser Head Installation

- ① Place the cutting head horizontally, remove the dust cover, and peel off the dust sticker; as shown in Figure 2.1.



Figure 2.1

- ② Align the Q+ output head with the corresponding pin slot. As shown in Figure 2.2:




Figure 2.2

Attention: In case the fiber head is with original dust-proof gasket, users can choose whether install dust-proof cover or not according to the actual condition.

Chapter 4 Product Debugging

4.1 Focusing Instructions (Example: FSCUT2000C (Pulse System))

Focus Reset - After powering up the machine, the fourth axis should reset first to bring the focus to the zero position. Below is the cutting head platform parameter configuration for collimation 100/focus 200:




Figure 2.3

① Open the software configuration platform, set the focus retraction distance to 30mm (can be slightly adjusted according to the actual conditions), to align the collimation focus at the zero scale position (as shown in Cypcut, Figure 2.3).

Attention: The retraction distance can be slightly adjusted according to the actual cutting focus.

4.1.1 GH15/20/30B Cypcut Platform Configuration

100 collimation, 200 focus:

Maximum focus adjustment range:	-39mm to 30mm;
Pulse equivalent:	every 8mm movement corresponds to 10,000 pulses;
Return to home direction:	Forward;
Retraction distance:	30mm;
Limit logic:	Normally open;


100 collimation, 250 focus:

Maximum focus adjustment range:	-60mm to 50mm;
Pulse equivalent:	Every 12.5mm movement corresponds to 10,000 pulses;
Return to home direction:	Forward;
Retraction distance:	50mm;
Limit logic:	Normally open;

100 collimation, 300 focus:

Maximum focus adjustment range:	-85mm to 70mm
Pulse equivalent:	Every 18mm movement corresponds to 10,000 pulses;
Return to home direction:	Forward;
Retraction distance:	70mm;
Limit logic:	Normally open;

4.1.2 Alarm Signal Configuration



Alarm configuration

Emergency stop button: ☐ NO ☐ NC

Maintenance switch: ☐ NO ☐ NC

Maximum speed in maintenance mode: 3000 mm/s

Maximum power in maintenance mode: W

Maximum allowed deviation for gantry synchronization: mm

☐ Alarm for excessive deviation in dual drive axle position

Allowed deviation: mm

Duration: milliseconds

Maximum deviation: mm

☐ All alarms must be manually cleared

☐ Lifter alarms must be confirmed before allowing axis movement.

☒ Display warning messages in the title bar when the machine tool is in motion:

When the machine tool is operating, it is strictly prohibited to reach any part of the hand or body into the machine!

Custom input alarm:

Single input port alarm Single input port warning 4-digit code alarm

Alarm description	Port number	Level detection	Filtering time
Cutting head alarm	15	☐ NO ☐ NC	0

☒ Processing not allowed

☒ Light emission not allowed

☒ Following not allowed

☒ Homing not allowed

☒ Movement not allowed


☒ X-axis inching not allowed

☒ Y-axis inching not allowed

Set input port IN15 as the cutting head alarm signal, logic normally open, IO customized to whatever port is connected to the corresponding input port.

4.2 FSCUT8000 System Configuration (Bus System)

4.2.1 Focus Control Configuration and Limit Configuration



GH15/20/30B Cypcut Platform Configuration

100 collimation, 200 focus:

Maximum focus adjustment range:	-39mm to 30mm;
Lead screw pitch:	8mm;
Pulses per revolution:	10,000;
Positive limit:	A13;
Negative limit:	A14;
Limit logic:	Normally open;
Return to home direction:	Forward;
Retraction distance:	30mm;

GH15/20/30B Cypcut Platform Configuration

100 collimation, 250 focus:

Maximum focus adjustment range:	-60mm to 50mm;
Lead screw pitch:	13mm;
Pulses per revolution:	10,000;
Positive limit:	A13;
Negative limit:	A14;
Limit logic:	Normally open;
Return to home direction:	Forward;
Retraction distance:	50mm;

100 collimation, 300 focus:

Maximum focus adjustment range:	-85mm to 70mm
Lead screw pitch:	18mm;
Pulses per revolution:	10,000;
Positive limit:	A13;
Negative limit:	A14;
Limit logic:	Normally open;
Return to home direction:	Forward;
Retraction distance:	70mm;

4.2.2 Alarm Signal Configuration

 Bus scan
  Axis configuration
  Home position
  Laser
  Cutting head
  Auxiliary gas
  Alarm
  Exchange worktable
  General input
  General output
  IO list
  Water chiller
  Wireless handheld box
  Maintenance
  Advanced configuration
  Parameter save

Custom input alarm

External emergency stop input

0

NO NC

Internal emergency stop output

0

NO NC

Front grate alarm input

0

NO NC

☐ Detect front grate only when lights are off and machine is moving

Rear grate alarm input

0

NO NC

Maintenance switch

0

NO NC

Maintenance mode XY axis maximum speed

200

mm/s

Maintenance mode Z axis maximum speed

100

mm/s

Maintenance mode maximum power

1000

W

Safety mode

Maximum no-load speed in safety mode

50

mm/s

☐ Exchange worktable prohibited in safety mode

☐ All alarms must be manually cleared during processing
 ☐ Hight controller alarms must be confirmed before allowing axis movement.

Single input port alarm

Single input port warning

4-digit code alarm

Add

Delete

Alarm description	Port number	Level detection	Filtering time
Cutting head alarm	A15	NO NC	0 ms

Processing not allowed

☒ Light emission not allowed
 ☒ Following not allowed
 ☒ Homing not allowed
 ☒ XY movement not allowed
 ☒ X-axis inching not allowed
 ☒ Y-axis inching not allowed
 ☒ XYZ movement not allowed

Cause:

Solution

Set input port IN15 as the cutting head alarm signal, logic normally open, IO customized to whatever port is connected to the corresponding input port.

4.3 LS6000M Non-Bus System Configuration

4.3.1 W-Axis Parameter Configuration

Common parameters
System parameters
Follower control
Laser settings
Regular maintenance reminder for machine tools

Parameter overview

- Basic machine tool parameters
 - 1.0 Axis parameter settings
 - 1.0.0 X-axis parameters
 - 1.0.1 Y-axis parameters
 - 1.0.2 Z-axis parameters
 - 1.0.3 W-axis parameters
 - 1.1 Home position setting
 - 1.2 Error compensation settings
- Speed and precision control
- External device control
- Advanced function parameters

Search

Name	Value	Unit	Effective time
1.0.3 W-axis parameters			
Encoder direction (W)	1		Effective immediately
Axis direction (W)	1		Effective immediately
Pulse equivalent (W)	0.0008	mm/p	Effective immediately
Command pulse count per revolution (W)	10000		Effective immediately
Feedback pulse count per revolution (W)	4000		Effective immediately
Soft limit upper value (W)	30	mm	Effective immediately
Soft limit lower value (W)	-39	mm	Effective immediately
Enable soft limit protection (W)	Yes		Effective immediately
Maximum axis speed (W)	6000	mm/min	Effective immediately

Manufacturer

Parameter name: Maximum axis speed (W)
Value: 6000mm/min
Description: Maximum speed of W axis

Drawing
Machining
Process
Monitoring
Operation report
Settings
Maintenance
Advanced

GH15/20/30B Weihong Platform Configuration

100 collimation, 200 focus:

Encoder Direction:	1;
Axis direction:	1;
Pulse equivalent:	0.0008;
Pulses per revolution:	10,000;
Feedback pulses per revolution:	4000;
Retraction distance:	30;
Upper limit of soft limits:	30;
Lower limit of soft limits:	-39;
Soft limit protection enabled:	Yes;
Maximum axis speed:	6000mm/s;

GH15/20/30B Weihong Platform Configuration


100 collimation, 250 focus:

Encoder Direction:	1;
Axis direction:	1;
Pulse equivalent:	0.00125;
Pulses per revolution:	10,000;
Feedback pulses per revolution:	4000;
Retraction distance:	50;
Upper limit of soft limits:	50;
Lower limit of soft limits:	-60;
Soft limit protection enabled:	Yes;
Maximum axis speed:	6000mm/s;

100 collimation, 300 focus:

Encoder Direction:	1;
Axis direction:	1;
Pulse equivalent:	0.0018;
Pulses per revolution:	10,000;
Feedback pulses per revolution:	4000;
Retraction distance:	70;
Upper limit of soft limits:	70;
Lower limit of soft limits:	-85;
Soft limit protection enabled:	Yes;
Maximum axis speed:	6000mm/s;

4.3.2 W-Axis Alarm Signal Association



Universal alarm bar, select cutting head alarm, associate address. Select controller, for example EX41A, choose port X03, customize IO to whichever port and connect to the corresponding input port.

External devices

Port settings

Log list

Address	Polarity	Sampling	Description
LD21E-04.Fln6	NO	S:1ms	Follower error occurring
LD21E-04.Fln7	NO	S:1ms	Floating head calibration in progress
LD21E-04.Fln8	NO	S:1ms	Follower not calibrated
LD21E-04.Fln9	NO	S:1ms	Frog jumping
LD21E-04.Fln10	NO	S:1ms	Frog jump command error
LD21E-04.Fln11	NO	S:1ms	Touching plate
LD21E-04.Fln12	NO	S:1ms	Follower in position
LD21E-04.Fln13	NO	S:1ms	Follower lower limit
LD21E-04.Fln14	NO	S:1ms	Capacitance surge
LD21E-04.Fln15	NO	S:1ms	Excessive penetration at edge
LD21E-04.Fln16	NO	S:1ms	Follower upper limit
LD21E-04.Fln18	NO	S:1ms	Reached plate surface position
LD21E-04.Fln19	NO	S:1ms	Nozzle bottom or side close to plate
EX41A.X00	NO	S:4ms	W-axis positive limit
EX41A.X01	NO	S:4ms	W-axis negative limit
EX41A.X02	NO	S:4ms	W-axis mechanical origin
EX41A.X03	NO	S:4ms	Cutting head alarm
EX41A.X04	NO	S:4ms	Low lubrication pressure
EX41A.X07	NO	S:1ms	Time reversal anomaly
EX31A.X00	NO	S:4ms	Exchange worktable
EX31A.X01	NO	S:4ms	Release bed
EX31A.X02	NO	S:4ms	Bed released
EX31A.X05	NO	S:4ms	Exchange table locked
EX31A.X06	NC	S:4ms	Safety door in position
EX31A.X07	NO	S:4ms	Z-axis negative limit (upper)
EX31A.X08	NO	S:4ms	Lower table entry
EX31A.X09	NO	S:4ms	Upper table entry

Output port

LD21E-04.Axis0_On

LD21E-04.Axis1_On

LD21E-04.Axis2_On

LD21E-04.Axis3_On

X-axis servo enabled

Y-axis servo enabled

Z-axis servo enabled

Y2-axis servo enabled

Test on

Test off

Cancel test

Cancel all

Filtering

Change polarity

Machining

Process

Monitoring

Operation

Settings

Maintenance

Advanced

EX41A.X00 NO (normally open) W-Axis Positive Limit

EX41A.X01 NO (normally open) W-Axis Negative Limit

EX41A.X03 NO (normally open) Cutting Head Alarm

4.4 LS6000M Bus System Configuration

4.4.1 W-Axis Parameter Configuration

Common parameters
System parameters
Driver settings
Follower control
Laser settings
Regular maintenance reminder for machine tools

Parameter overview

- Basic machine tool parameters
 - 1.0 Axis parameter settings
 - 1.0.0 X-axis parameters
 - 1.0.1 Y-axis parameters
 - 1.0.2 Z-axis parameters
 - 1.0.3 W-axis parameters
 - 1.1 Home position setting
 - 1.2 Error compensation settings
- Speed and precision control
- External device control
- Advanced function parameters

Name
Value
Unit
Effective time

1.0.3 W-axis parameters

Driver station address 1 (W)	5		Effective on restart
Driver station address 2 (W)	15		Effective on restart
Slave address internal axis offset address (W)	0		Effective on restart
Axis direction (W)	1		Effective immediately
Leadscrew pitch (W)	8	mm	Effective immediately
Encoder resolution (W)	13		Effective immediately
Encoder type (W)	0		Effective immediately
Electronic gear ratio numerator (W)	8192		Effective immediately
Electronic gear ratio denominator (W)	10000		Effective immediately
Soft limit upper value (W)	30	mm	Effective immediately
Soft limit lower value (W)	-39	mm	Effective immediately
Enable soft limit protection (W)	Yes		Effective immediately
Maximum axis speed (W)	6000	mm/min	Effective immediately
Check axis encoder error (W)	否		Effective immediately
Encoder steady state tolerance (W)	0.1	mm	Effective immediately
Encoder dynamic tolerance (W)	40	mm	Effective immediately

Manufacturer

Parameter name: Maximum axis speed (W)
Value: 6000mm/min
Description: Maximum speed of W axis

Machining
Process
Monitoring
Operation report
Settings
Maintenance
Advanced

GH15/20/30B Weihong Platform Configuration

100 collimation, 200 focus:

Driver slave address 1 (W):	5;
Driver slave address 2 (W):	15;
Axis direction:	1;
Lead screw pitch:	8;
Encoder resolution:	13 bits;
Encoder type:	0;
Electronic gear ratio numerator (W):	8192;
Electronic gear ratio denominator (W):	10,000;;
Retraction distance:	30;
Upper limit of soft limits (W):	30;
Lower limit of soft limits (W):	-39;
Soft limit protection enabled (W):	Yes;
Maximum axis speed (W):	6000mm/min;

GH15/20/30B Weihong Platform Configuration


100 collimation, 250 focus:

Driver slave address 1 (W):	5;
Driver slave address 2 (W):	15;
Axis direction:	1;
Lead screw pitch:	12.5;
Encoder resolution:	13 bits;
Encoder type:	0;
Electronic gear ratio numerator (W):	8192;
Electronic gear ratio denominator (W):	10,000;;
Retraction distance:	50;
Upper limit of soft limits (W):	50;
Lower limit of soft limits (W):	-60;
Soft limit protection enabled (W):	Yes;
Maximum axis speed (W):	6000mm/min;

100 collimation, 300 focus:

Driver slave address 1 (W):	5;
Driver slave address 2 (W):	15;
Axis direction:	1;
Lead screw pitch:	18;
Encoder resolution:	13 bits;
Encoder type:	0;
Electronic gear ratio numerator (W):	8192;
Electronic gear ratio denominator (W):	10,000;;
Retraction distance:	70;
Upper limit of soft limits (W):	70;
Lower limit of soft limits (W):	-85;
Soft limit protection enabled (W):	Yes;
Maximum axis speed (W):	6000mm/min;

4.4.2 W-Axis Alarm Signal Association



Universal alarm bar, select cutting head alarm, associate address. Select controller, for example EX41A, choose port X03, customize IO to whichever port and connect to the corresponding input port.

External devices

Port settings

Log list

Address	Polarity	Sampling	Description
LD21E-04.Fln6	NO	S:1ms	Follower error occurring
LD21E-04.Fln7	NO	S:1ms	Floating head calibration in progress
LD21E-04.Fln8	NO	S:1ms	Follower not calibrated
LD21E-04.Fln9	NO	S:1ms	Frog jumping
LD21E-04.Fln10	NO	S:1ms	Frog jump command error
LD21E-04.Fln11	NO	S:1ms	Touching plate
LD21E-04.Fln12	NO	S:1ms	Follower in position
LD21E-04.Fln13	NO	S:1ms	Follower lower limit
LD21E-04.Fln14	NO	S:1ms	Capacitance surge
LD21E-04.Fln15	NO	S:1ms	Excessive penetration at edge
LD21E-04.Fln16	NO	S:1ms	Follower upper limit
LD21E-04.Fln18	NO	S:1ms	Reached plate surface position
LD21E-04.Fln19	NO	S:1ms	Nozzle bottom or side close to plate
EX41A.X00	NO	S:4ms	W-axis positive limit
EX41A.X01	NO	S:4ms	W-axis negative limit
EX41A.X02	NO	S:4ms	W-axis mechanical origin
EX41A.X03	NO	S:4ms	Cutting head alarm
EX41A.X04	NO	S:4ms	Low lubrication pressure
EX41A.X07	NO	S:1ms	Time reversal anomaly
EX31A.X00	NO	S:4ms	Exchange worktable
EX31A.X01	NO	S:4ms	Release bed
EX31A.X02	NO	S:4ms	Bed released
EX31A.X05	NO	S:4ms	Exchange table locked
EX31A.X06	NC	S:4ms	Safety door in position
EX31A.X07	NO	S:4ms	Z-axis negative limit (upper)
EX31A.X08	NO	S:4ms	Lower table entry
EX31A.X09	NO	S:4ms	Upper table entry

Output port

LD21E-04.Axis0_On	X-axis servo enabled
LD21E-04.Axis1_On	Y-axis servo enabled
LD21E-04.Axis2_On	Z-axis servo enabled
LD21E-04.Axis3_On	Y2-axis servo enabled

Test on

Test off

Cancel test

Cancel all

Filtering

Change polarity

Machining

Process

Monitoring

Operation

Settings

Maintenance

Advanced


EX41A.X00 NO (normally open) W-Axis Positive Limit

EX41A.X01 NO (normally open) W-Axis Negative Limit

EX41A.X03 NO (normally open) Cutting Head Alarm

4.5 Centering Alignment Instructions

- ① To achieve a good joint-cutting effect, the laser beam **SHOULD** be kept in the center of the nozzle. When it deviates from the center of the nozzle, it needs to be centered through the beam centering module, as shown in Figure 2.4.



2.4

Note: When the centering knob is turned clockwise, the center of the lens moves inward.

When the centering knob is turned counterclockwise, the center of the lens moves outward.

4.6 Mobile APP Operation Instructions

4.6.1 Mobile APP Software Installation.

- ① After installation, the icon appears as shown in Figure 2.5; continue by clicking 'Install', and the icon after installation is shown in Figure 2.6. This APP currently only supports installation on Android devices.




Figure 2.5



Figure 2.6

Icon is displayed after installation

4.6.2 APP Software Connection.



Figure 2.7

- ① Click the Bluetooth icon to open the Bluetooth connection interface, as shown in Figure 2.7.




Figure 2.8

- ② Start scanning; if nothing is displayed, click it for another more times, as shown in Figure 2.8.




Figure 2.9

- ③ After the device is scanned, select the device to connect and click the [Connect Device] button, and then the mobile phone can communicate with the device in real time, as shown in Figure 2.9.

4.6.3 Software Introduction.


- ① After running the GH15B APP, the progress bar color on the main interface will change according to the actual temperature value monitored, as shown in Figure 3.0.
- Green: The lens temperature is monitored to be normal and the software can be used normally.
- Yellow: The lens temperature is too high, and attention should be paid to check if the lens is contaminated.
- Red: The lens temperature is too high and the software cannot continue to be used. The machine must be stopped for checking.



Figure 3.0

4.6.4 Temperature Parameter Setting and Modification of Equipment Name.


- ① This APP has temperature setting function. You can set different temperature thresholds according to actual situation . Click "Parameter Setting" and input the password "85225225" to enter the temperature settings interface, as shown in Figure. 3.1.
- ② The software can also monitor the real-time dimensions of the electronic scale, internal temperature and humidity of the cavity, cutting gas pressure, and detect any leaks in the cutting gas.



**Click on the
manufacturer settings
option,
Password: 85225225**

Figure 3.1

② Enter temperature setting interface to set the temperature according to the actual conditions. The forewarning value must be lower than the alarm value. After settings, click "Confirm". This window also allows for setting of the cutting head encoding; when the Bluetooth mode is disconnected, it automatically switches to the 5G model state, as shown in Figure 3.2:



The screenshot shows a software interface for temperature settings. At the top, there are three buttons: 'Connected' (with a star icon), 'Bluetooth device', and 'Disconnect'. Below these is a 'Temperature optimization' toggle switch, which is currently turned on. The main section contains several settings, each with a label, a numeric input field, and an annotation box. The settings are: 'Bluetooth name' (value: PIC282023041364003, annotation: Equipment name Code Input port), 'Cutting protective lens pre-alarm threshold' (value: 50, annotation: Yellow indicator - forewarning), 'Cutting protective lens alarm threshold' (value: 55, annotation: Red indicator - alarm), 'Upper protective lens pre-alarm threshold' (value: 50, annotation: Yellow indicator - forewarning), 'Upper protective lens alarm threshold' (value: 55, annotation: Red indicator - alarm), 'Focusing protective lens pre-alarm threshold' (value: 50, annotation: Yellow indicator - forewarning), 'Focusing protective lens alarm threshold' (value: 55, annotation: Red indicator - alarm), 'Focusing lens pre-alarm threshold' (value: 50, annotation: Yellow indicator - forewarning), 'Focusing lens alarm threshold' (value: 55, annotation: Red indicator - alarm), 'Nozzle temperature pre-alarm threshold' (value: 50, annotation: Yellow indicator - forewarning), and 'Nozzle temperature alarm threshold' (value: 55, annotation: Red indicator - alarm). At the bottom, there is a 'Confirm settings' button.

Setting	Value	Indicator
Bluetooth name	PIC282023041364003	Equipment name Code Input port
Cutting protective lens pre-alarm threshold	50	Yellow indicator - forewarning
Cutting protective lens alarm threshold	55	Red indicator - alarm
Upper protective lens pre-alarm threshold	50	Yellow indicator - forewarning
Upper protective lens alarm threshold	55	Red indicator - alarm
Focusing protective lens pre-alarm threshold	50	Yellow indicator - forewarning
Focusing protective lens alarm threshold	55	Red indicator - alarm
Focusing lens pre-alarm threshold	50	Yellow indicator - forewarning
Focusing lens alarm threshold	55	Red indicator - alarm
Nozzle temperature pre-alarm threshold	50	Yellow indicator - forewarning
Nozzle temperature alarm threshold	55	Red indicator - alarm

Confirm settings

Figure 3.2

Chapter 5 Product Maintenance

5.1 Maintenance of Protective Lens

In case poor cutting performance occurs while cutting protective lens is normal, but burning points on the ceramic piece, the collimation protective lens or focus protective lens possibly is polluted or damaged. In this condition, please pull out the protective lens cartridge to check the lens. Before checking, use a clean cloth dampened with alcohol to wipe the exterior clean.

5.1.1 Disassembly and assembly of the first and second collimation protective lens, as shown in Figure 3.3.




Figure 3.3

(1) Disassembly and assembly of the first collimation protective lens, as shown in Figures 3.3, 3.4, and 3.5.




Figure 3.4




Figure 3.5

(2) Disassembly and assembly of the second collimation protective lens, as shown in Figures 3.3, 3.4, and 3.5.as shown in Fig. 3.5.




Figure 3.4




Figure 3.5



Figure 3.6



Figure 3.7

- ① Tools: Dust-free wiping swabs, isopropyl alcohol, dry and pure compressed air.
- ② Spray isopropyl alcohol onto the dust-free wiping swabs.
- ③ Gently pinch the both sides of the lens with the left thumb and index finger, and hold the wiping swabs with right hand to gently wipe both sides of the lens in a single direction from bottom to top or from left to right, As shown in Figure 3.5.
- ④ After wiping, blow the lens surface again with filled dry and pure compressed air to ensure that there are not foreign matters on the lens surface, as shown in Figure 3.6.
- ⑤ The cleansed lens must be installed into the cutting head's body as soon as possible or stored in other clean and sealed container.

5.1.2 Disassembly of Focus Protective Lens

Loosen the two M4×16 hexagon socket anti-falling screws, pull out the protective lens cartridge, and replace the protective lens (PMD34T5), as shown in Figures 3.8 and 3.9 below.

Loosen two M4×16 anti-falling screws and remove the focus protective lens.





Figure 3.8




Figure 3.9



Figure 4.1



Figure 4.2

- ① Tools: Dust-free wiping swabs, isopropyl alcohol, dry and pure compressed air.
- ② Spray isopropyl alcohol onto the dust-free wiping swabs.
- ③ Gently pinch the both sides of the lens with the left thumb and index finger, and hold the wiping swabs with right hand to gently wipe both sides of the lens in a single direction from bottom to top or from left to right, As shown in Figure 4.1.
- ④ After wiping, blow the lens surface again with filled dry and pure compressed air to ensure that there are not foreign matters on the lens surface, as shown in Fig. 4.2.
- ⑤ The cleansed lens must be installed into the cutting head's body as soon as possible or stored in other clean and sealed container.

5.1.3 Disassembly, Assembly, and Replacement of Cutting Protective Lens

Press the latch, open the outer cover, remove the cutting protective lens cartridge, replace the protective lens, and remember to close the outer cover before replacing the lens and then open it again after the replacement to insert the cartridge back into the cutting head, preventing prolonged exposure of the laser head internals.




Figure 4.3



Figure 4.4




Figure 4.5

- ① Tools: Dust-free wiping swabs, isopropyl alcohol, dry and pure compressed air.
- ② Spray isopropyl alcohol onto the dust-free wiping swabs.
- ③ Gently pinch the both sides of the lens with the left thumb and index finger, and hold the wiping swabs with right hand to gently wipe both sides of the lens in a single direction from bottom to top or from left to right, As shown in Figure 4.4.
- ④ After wiping, blow the lens surface again with filled dry and pure compressed air to ensure that there are not foreign matters on the lens surface, as shown in Figure. 4.5.
- ⑤ The cleansed lens must be installed into the cutting head's body as soon as possible or stored in other clean and sealed container.

Attention: When cleaning and replacing the protective lens, avoid the grease on hands or dust in the environment from contaminating the protective lens . In principle, the focus lens, collimation lens and cutting lens are generally forbidden to be disassembled. If lenses may be contaminated, users can first test the lenses with ceramic piece, or contact with our technical staff if necessary

5.2 Maintenance of Sensory Components.

5.2.1 Cleaning of the Ceramic Ring.

- ① Remove the nozzle counterclockwise, as shown in Figure. 4.6.
- ② Remove the ceramic clamp ring counterclockwise, as shown in Figure 4.6.
- ③ Remove the ceramic body vertically downward, as shown in Figure. 4.6.




Figure 4.6

5.2.2 Cleaning of the Ceramic Ring.

- ① Take out the ceramic and clean it with anhydrous alcohol or isopropyl alcohol, as shown in Figure 4.7.
- ② Spray isopropyl alcohol onto the dust-free swab, remove the ceramic ring and clean it with the swab, as shown in Fig. 4.8.
- ③ After that, clean the ceramic ring with dry and pure compressed air to ensure that the ceramic surface is clean and dry without moisture before installation, as shown in Figure 4.9.



Figure 4.7



Figure 4.8



Figure 4.9

Note: Cleanliness of ceramic surface is directly related to the operating performance of the following system. It is necessary to clean timely the dirt on the ceramic surface in order to ensure the working performance of the system.



Shenzhen Ospri Intelligent Technology Co.,Ltd

Tel: 0755-85225225

Fax: 4008266163-19300

e-Mail: mj.chen@sz-osprey.com

Add: Room 1001, Building A, No.4 Factory, Baolong Zhizaoyuan,
New Energy 1st Road, Baolong Community, Longgang District,
Shenzhen